

DRAWN BY: DVM ω Ū 1. IT IS THE PROPERTY OWNERS RESPONSIBILITY TO DISCONNECT EXISTING DOWNSPOUT LATERAL FROM THE BOROUGH'S SANITARY SEWER, REFERENCE DETAIL 1 THIS SHEET. GENERAL COLLECTION/CONVEYANCE FACILITIES SHOULD NOT BE INSTALLED PARALLEL AND CLOSE TO THE TOP OR BOTTOM OF A MAJOR EMBANKMENT TO AVOID THE POSSIBILITY OF EMBANKMENT FAILURE. ALL SITES SHALL PROVIDE DRAINAGE AWAY FROM AND AROUND THE STRUCTURE IN ORDER TO PREVENT ANY POTENTIAL FLOODING DAMAGE. THIS INCLUDES INSTALLING A NEW DOWNSPOUT LATERAL THAT DOES NOT FLOOD YOUR DOWNSPOUT LATERALS SHALL BE INSTALLED IN ACCORDANCE WITH THE BOROUGH'S STORMWATER MANAGEMENT RULES AND REGULATIONS. CONTACT THE BOROUGH FOR GUIDANCE PRIOR TO INSTALLING, REPLACING, OR REPAIRING DOWNSPOUT LATERALS. NEIGHBORS PROPERTY. NOTES: REVISIONS: EXSITING DOWNSPOUT BUILDING SEWER CONNECTION ANTONACCI DESIGN TYPE OF CONNECTION FITTINGS TO BE DETERMINED BY PIPE MATERIAL REPLACE WYE FITTING WITH STRAIGHT PIPE SECTION ASSOCIATES, DOWNSPOUT PROPOSED DOWNSPOUT BUILDING SEWER BUILDING SEWER DISCONNECT INC. MANOR FROM SERVICE LATERAL DISCONNECT DOWNSPOUT FLOOR DRAIN/TOILET BOROUGH


DATE: 2-11-20 SCALE: N.T.S.

220 SOUTH FIFTH STREET JEANNETTE, PA. 15644
724-527-7771 724-527-1599 FAX
EDWARD.ANTONACCI @ VERIZON.NET

DOWNSPOUT DISCONNECT

BS5

PPROVED BY:



DRAWN BY: DVM
DATE: 2-11-20
SCALE: N.T.S.

REVISIONS:

ANTONACCI DESIGN

ASSOCIATES,

220 SOUTH FIFTH STREET JEANNETTE, PA. 15644
724-527-7771 724-527-1599 FAX
EDWARD.ANTONACCI @ VERIZON.NET

PIPE BEDDING DETAILS

MANOR BOROUGH

BS4

PPROVED BY:

